




# VELLUTO ME/KI

## Chart of After Care Symbols




### Washing Process

	Maximum washing temperature 95° C, normal process
	Maximum washing temperature 70° C, normal process
	Maximum washing temperature 60° C, normal process
	Maximum washing temperature 60° C, mild process
	Maximum washing temperature 50° C
	Maximum washing temperature 50° C, mild process
	Maximum washing temperature 40° C
	Maximum washing temperature 40° C, mild process
	Maximum washing temperature 40° C, very mild process
	Maximum washing temperature 30° C
	Maximum washing temperature 30° C, mild process
	Maximum washing temperature 30° C, very mild process
	Wash by hand, maximum temperature 40° C
	Do not wash





### Bleaching Process

	Any bleaching agent allowed
	Only oxygen/non-chlorine bleach allowed
	Do not bleach










### Tumble Drying Process

	Tumble drying possible, normal temperature, maximum exhaust temperature 80° C
	Tumble drying possible, drying at lower temperature, maximum exhaust temperature 60° C
	Do not tumble dry


### Ironing Process

	Iron at a maximum sole-plate temperature of 200° C
	Iron at a maximum sole-plate temperature of 150° C
	Iron at a maximum sole-plate temperature of 110° C without steam, steam ironing may cause irreversible damage
	Do not iron

### Professional Textile Care Process

	Professional dry cleaning in tetrachloroethene and all solvents listed for the symbol F normal process
	Professional dry cleaning in tetrachloroethene and all solvents listed for the symbol F mild process
	Professional dry cleaning in hydrocarbons (distillation temperature between 150° C and 210° C, flash point between 38° C and 70° C), normal process
	Professional dry cleaning in hydrocarbons (distillation temperature between 150° C and 210° C, flash point between 38° C and 70° C), mild process
	Do not dry clean
	Professional wet cleaning, normal process
	Professional wet cleaning, mild process
	Professional wet cleaning, very mild process
	Do not professional wet clean

### Special Care

	MERCIS symbol that represents gentle removal of stains with a cloth
---	---